

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N570935521

FACILITY: MDNR Litigation UP District		SRN / ID: N5709
LOCATION: 47 US 41 North, BARAGA		DISTRICT: Upper Peninsula
CITY: BARAGA		COUNTY: BARAGA
CONTACT:		ACTIVITY DATE: 07/13/2016
STAFF: Joel Asher	COMPLIANCE STATUS:	SOURCE CLASS:
SUBJECT: Soil and groundwater treatment system		
RESOLVED COMPLAINTS:		

On 7/13/2016, I met with Mr. Clif Clark, District Supervisor of the Remediation and Development Division in the Upper Peninsula District Office. We discussed PTI #638-91B. This permit was issued for a soil and groundwater treatment system to be located at the Department of Natural Resources District Office.

Mr. Clark stated this unit has been removed for many years. A note will be sent to Ms. Sue Thelen in the Permit Section to void PTI # 638-91B.

NAME



DATE

7/13/16

SUPERVISOR

