## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

## **FCE Summary Report**

Facility:	CONTINENTAL ALUMINUM		SRN:	N6013
Location: 2	9201 MILFORD RD		District :	Warren
			County:	OAKLAND
City: NE	W HUDSON State: MI Zip Code: 4816	5 <b>Comp</b> Status	liance s :	Compliance
Source Class : SM OPT OUT Staff : Iranna Konanahalli				
FCE Begin Da	nte: 4/10/2019	FCE Dat	Completion e :	9/22/2021
Comments: Currently Continental is in compliance with the permit and MACT 3R. Continental is idled for a foreseeable future. Continental may or may not restart.				

## **List of Partial Compliance Evaluations:**

Activity Date	Activity Type	Compliance Status	Comments
09/21/2021	On-site Inspection	Compliance	FY 2021 SM CMS scheduled inspection of Continental Aluminum ("Continental"), an aluminum scrap recycling and remelting facility
08/10/2021	MACT (Part 63)	Compliance	Semi-Annual Secondary Summary Report - January 1, 2021 through June 30, 2021.
07/08/2021	Other Non ROP	Compliance	Quarterly COMS Report for 1st Quarter 2021; Permit No. 504-96F.
05/29/2021	Complaint Investigation		Phone follow-up to PEAS complaint #26510
05/27/2021	MAERS	Compliance	MAERS Report Submission
05/27/2021	Other Non ROP	Compliance	2021 MDEQ Rotary Report RO1 - 1st quarter (new permit) 2021 MDEQ DEOX Report RV1- 1st quarter (new permit) 2021 MDEQ Reverb 2 Report - 1st quarter (new permit)
05/14/2021	Complaint Investigation	Compliance	Resolve complaints
02/10/2021	Other Non ROP	Compliance	4th Quarter 2020 Summary Report SSMP – Malfunction List & Response Procedure Emission Unit RV-2 COMS System (RV-2 & Baghouse Equipment)
01/28/2021	MACT (Part 63)	Compliance	Semi-Annual Secondary Summary Report - July 1, 2020 through December 31, 2020

Activity Date	Activity Type	Compliance Status	Comments
12/08/2020	Other	Compliance	February 06, 2020, Violation Resolution letter via e-mail (Tue 12/8/2020 8:49 AM)
08/25/2020	MACT (Part 63)	Compliance	Semi-Annual Secondary Summary Report - January 1, 2020 through June 30, 2020.
06/15/2020	Excess Emissions (CEM)	Compliance	1st Quarter 2020 Summary Report for Gaseous and Opacity Excess Emission and Monitoring System Performance.
05/26/2020	Other Non ROP	Compliance	1st Quarter 2020 Summary Report SSMP – Malfunction List & Response Procedure Emission Unit RV-2 COMS System (RV-2 & Baghouse Equipment)
02/27/2020	On-site Inspection	Non Compliance	FY 2019 SM CMS scheduled inspection of Continental Aluminum ("Continental"), New Hudson
01/22/2020	MACT (Part 63)	Compliance	Semi-Annual Secondary Summary Report - July 1, 2019 through December 31, 2019
01/09/2020	Other Non ROP	Compliance	2019 MDEQ Rotary Report - 3rd quarter (New Permit) 2019 MDEQ DEOX Report - 3rd quarter (New Permit) Flux and lime rates show comliance
09/06/2019	Complaint Investigation	Non Compliance	FY 2019 Odor Complaints: C-19-00337-20181102, C-19-01359-0207, C-19-01848-0708, C-19-02315-0908, C-19-02316-0908, C-19-02317-0908, C-19-02327-0908, C-19-02330-0908, C-19-02363-0916, C-19-02366-0916, C-19-02423-0920.
08/18/2019	Other Non ROP	Compliance	3rd and 4th Quarter 2019 Summary Report SSMP – Malfunction List & Response Procedure Emission Unit RV-2 COMS System (RV-2 & Baghouse Equipment)
07/24/2019	MACT (Part 63)	Compliance	Semi-Annual Secondary Summary Report - January 1, 2019 through June 30, 2019.
07/10/2019	Scheduled Inspection	Compliance	FY 2019 SM CMS scheduled inspection of Continental Aluminum ("Continental")

Activity Date	Activity Type	Compliance Status	Comments
07/05/2019	Other	Compliance	July 2019 RV2 stack test to set operating parameters per the permit & NESHAP / MACT 3R and, also, to determine compliance with the permit and NESHAP / MACT 3R limits (e.g. D/F, PM, HCI, HF).
05/03/2019	Complaint Investigation	Non Compliance	On-site odor evaluation in response to several complaints.
04/22/2019	Complaint Investigation	Compliance	On-site odor evaluation in response to several complaints.

Name: Standard Date: October 7, 2021 Supervisor: