## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

## FCE Summary Report

Facility:	RIVERSIDE - CUSTER ANTRIM CPF & CO2 PLANT					SRN:	N6100
Location: SW SW SEC 19 T29N R6W						District :	Cadillac
						County:	ANTRIM
City:	MANCELONA	State: M	Zip Code :		Compl Status		Compliance
Source Class: SM OPT OUT Staff: Jodi Lindgren							ndgren
FCE Begin	Date: 1/1/2020				FCE Date	Completion :	3/29/2021
Comments	: FY21 FCE						

## **List of Partial Compliance Evaluations:**

Activity Date	Activity Type	Compliance Status	Comments
03/29/2021	On-site Inspection	Compliance	On-site facility inspection and records review for compliance with PTI 550-97B
01/21/2021	MAERS	Compliance	See MAERS for further info.
04/27/2020	MAERS	Compliance	No 2018 emissions report. 2019 Emissions estimated by Facility using MAERS EF for all but CO and NOx for compressor engine. sgl

Name:	Date:	Supervisor:		
			Page 1 of 1	