DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: RIVERSIDE - CHARLTON EAST CPF							SRN:	N6121
Location: NE NW NE SEC 3 T29N R1W						District :	Gaylord	
							County:	OTSEGO
1 -	CHARLTON WP	State:	MI	Zip Code :	49751	Comp Status		Compliance
Source Class: SM OPT OUT Staff: Becky Radulski								
FCE Begin I	Date : 4/18/21					FCE Date	Completion :	4/18/2022
Comments	: FY22 FCE							

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
04/18/2022	On-site Inspection	Compliance	FY22 inspection and records review
01/24/2022	MAERS	•	2020 MAERS, See MAERS for any review comments

Name: echy Raduski Date: 7-6-23 Supervisor: