


DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Site Review

N612728385

FACILITY: BREITBURN OPERATING LP - CHESTER 7-11		SRN / ID: N6127
LOCATION: NE SE SEC 12 T30N R3W, BAGLEY TWP		DISTRICT: Cadillac
CITY: BAGLEY TWP		COUNTY: OTSEGO
CONTACT: Carolann Knapp, Environmental Specialist		ACTIVITY DATE: 01/13/2015
STAFF: Caryn Owens	COMPLIANCE STATUS: Compliance	
SUBJECT: Void request for PTI 685-96, and site visit to verify facility is shut-in.		SOURCE CLASS: MINOR
RESOLVED COMPLAINTS:		

On Tuesday, January 13, 2015, Caryn Owens and Shane Nixon of the DEQ-AQD visited the Breitburn Operating, LP – Chester 7-11 (N6127) to verify the facility has been shut-in. When DEQ arrived at the facility, the south wall was gone, and the compressor was completely removed from the facility. Pipes leading to the iron sponge, storage tanks, and the separator inside the building were cut-off and disconnected. DEQ took photos that are attached.

Based on visual inspection and a request from Breitburn Operating from September 25, 2014, PTI 685-96 can be voided.




Image 1(Chester 7-11) : Shut-In Status

NAME Caryn Owens

DATE 1/13/15

SUPERVISOR [Signature]