



January 12, 2015, 2014

Mr. Rex I Lane

Senior Environmental Quality Analyst

Air Quality Division

7953 Adobe Road

Kalamazoo, MI 49009-5025

Dear Mr. Lane:

This letter is in response to Brembo North America Violation Notice dated November 10, 2014. Included in this response there are several documents that I believe address the violations. Those documents include:

- Drawing illustrating the paint line exhaust stacks
- List of corrective actions and current status
- Table of paint stacks listing description, Stack ID number, Height & Dia.

Additional to this e-mail response all of the above documents have been mailed to you as a hard copy.

If any other information is needed please contact me.

Sincerely,

Mark Kenworthy

HSE Manager
Brembo North America
29991 M-60 East
Homer, MI 49245
517 568-4398 Ext. 213