N6368 MANILA

# DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: On-site Inspection

N636867157

11000001101		
FACILITY: SRGGI Advanced Development Center		SRN / ID: N6368
LOCATION: 12620 DELTA DRIVE, TAYLOR		DISTRICT: Detroit
CITY: TAYLOR		COUNTY: WAYNE
CONTACT: Jim Herrmann , Environmental, Health, and Safety Manager		<b>ACTIVITY DATE:</b> 04/21/2023
STAFF: Jill Zimmerman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Onsite Inspection		
RESOLVED COMPLAINTS:		

DATE OF INSPECTION

April 21, 2023

TIME OF INSPECTION

9:30 am

**INSPECTED BY** 

Jill Zimmerman

PERSONNEL PRESENT

Jim Herrmann

Nick Vitale

### **BACKGROUND**

SRG Global was a former chrome plating facility, plating for the automotive industry.

#### COMPLAINT/COMPLIANCE HISTORY

No complaints have been received regarding this facility. No VN's have been issued for this facility.

# PROCESS EQUIPMENT AND CONTROLS

Currently, this facility has no operations occurring. The former chrome plating process, including approximately 74 tanks and a ventilation system has been removed from the facility. The roof has been repaired from where the ventilation equipment was removed.

#### INSPECTION NARRATIVE

On Friday April 14, 2023 I drove past the facility and observed the parking lot was vacant and it appeared no operations were occurring at this location.

After communicating with Mr. Jim Herrmann, we met at the facility on Friday April 21, 2023 at 9:30 am. When I arrived at the facility, I was told that production was stopped on November 7, 2022 and the equipment was removed on about December 26, 2022. I observed a large empty space where the equipment had once been located.

# APPLICABLE RULES/PERMIT CONDITIONS

This facility was operating under PTI 159-97B. This permit has been voided per the request of the facility after the equipment was removed.

MAERS REPORT REVIEW

NA

# FINAL COMPLIANCE DETERMINATION

SRG Global is no longer operating at this location. All equipment was removed and all operating permits have been voided.

NAME 101 C2

DATE 4128)2023 SUPERVISOR