

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : Ener Vest Operating ASE 6 CPF	SRN : N6431
Location : T30N-R2W, Section 32 NW/SE/SW Section 32	District : Cadillac
	County : OTSEGO
City : CHESTER TWP State: MI Zip Code : 49751	Compliance Status : Non Compliance
Source Class : SM OPT OUT	Staff : Shane Nixon
FCE Begin Date : 02/27/2016	FCE Completion Date : 2/27/2017
Comments : Engine stack height is not constructed in accordance with the requirements listed in the permit to install.	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
02/15/2017	Scheduled Inspection	Non Compliance	on-site inspection
01/17/2017	Other	Compliance	Partial compliance evaluation - Records review
03/22/2016	MAERS	Compliance	See MAERS database for further info.

Name: Shane Nixon **Date:** 2/27/17 **Supervisor:** _____