

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N645926019

| | | |
|---|-------------------------------|---------------------------|
| FACILITY: BIEHL EXCAVATING INC #162-98 | | SRN / ID: N6459 |
| LOCATION: SW1/4 SW1/4 SEC. 27, SAGOLA TWP | | DISTRICT: Upper Peninsula |
| CITY: SAGOLA TWP | | COUNTY: DICKINSON |
| CONTACT: Dave Dzurick , Foreman | | ACTIVITY DATE: 07/17/2014 |
| STAFF: Joe Scanlan | COMPLIANCE STATUS: Compliance | SOURCE CLASS: MINOR |
| SUBJECT: Unannounced inspection of portable gravel crusher. | | |
| RESOLVED COMPLAINTS: | | |

On 07/17/2014 I conducted an unannounced inspection of this portable gravel crusher. My contact was the foreman, Mr. Dave Dzurick. There was one other employee present running a front-end loader.

This crusher was crushing asphalt to be recycled at the Payne & Dolan C-19 permanent asphalt plant located on Kiiskila Road outside of Hancock. Mr. Dzurick stated that 7000 tons of asphalt had been ground since they had arrived at this location on 7/14 and it is expected they will finish with about 15,000 tons total by 7/21. Mr. Dzurick presented a copy of PTI #162-98 when requested.

A water tank was observed onsite and spray bars were being utilized to control fugitive dust emissions. Water is obtained from a well on site.

Mr. Dzurick stated no new equipment had been added since the previous inspection. The following equipment was observed to be in operation:

Primary Jaw Crusher--1000

Secondary Jaw Crusher--1001

Roll Crusher--1002

Conveyor--1101

All equipment is permitted under PTI #162-98.

No violations of the Air Pollution Control Rules or PTI #162-98 were observed during this inspection.




Image 1(2014 1) : Primary jaw crusher--1000




Image 2(2014 2) : Secondary jaw crusher




Image 3(2014_3) : Roll crusher--1002




Image 4(2014_4) : Conveyor #1--1101

NAME Joseph P. Seaman

DATE 7/22/14

SUPERVISOR _____