## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**ACTIVITY REPORT: Scheduled Inspection** 

FACILITY: A LINDBERG & SONS INC #83-99		SRN / ID: N6721
LOCATION: PN 3042 (2) CRUSHING PLANT #83-99, ISHPEMING		DISTRICT: Upper Peninsula
CITY: ISHPEMING		COUNTY: MARQUETTE
CONTACT: David Makinen , Foreman		ACTIVITY DATE: 07/01/2015
STAFF: Joe Scanlan	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Unannounced insp	pection for compliance with state air pollution control ru	iles.
RESOLVED COMPLAINTS:		The Marketine Control of the Control

INSPECTION DATE: 7/01/2015

DEQ STAFF: Joseph Scanlan

FACILITY: Portable Gravel Crusher (SRN: N6721;PTI#: 83-99)

FACILITY OWNER: A. Lindberg & Sons, Inc.

LOCATION: Alger Pit, about a mile south of M-28, just west of H03 (pit owned by the Alger County Road Commission)

INSPECTION: The unit had been on site for a couple of days prior to my arrival. The crusher was running at the time of inspection with three employees maintaining and feeding the unit. Two excavators were being operated, one feeding the primary jaw and the other handling finished product. Mr. David Makinen continues to be the crusher operator, as in the past. Mr. Makinen provided copies of PTI# 83-99 which was stored in a 3-ring binder in the equipment trailer. At the time of inspection approximately 13,000 Tons of 5/16<sup>th</sup> minus sand & 22A gravel had been crushed. A representative from U.P. Engineers & Assoc. was on site sampling the material to ensure it met MDOT specifications. A 2000-gallon water truck was on site and water was being sourced from a creek inlet to AuTrain Lake. The following equipment was on site:

- C-105 Crusher
- RS-20 Conveyor
- SP-19 Screen (rental)
- RS-25 Conveyor
- RS-19 Telescoping Conveyor

Visible Emissions readings have been submitted for all equipment (including rented screen SP-19).

SUMMARY: I observed no violations of the state air pollution control rules. Owner/Operator is in compliance.

the Minterest for that are in home and Minter Dance Minter Dancet activity Dancet accept A stirity ID-2454 7/0/201




Image 1(AL1) : RS-19 Telescoping conveyor



Image 2(AL2): RS-25 conveyor




Image 3(AL3): Rented screen SP-19



Image 4(AL4): RS-20 conveyor




Image 5(AL5): Primary jaw C-105

NAME Joseph Jensen

DATE 7 8 15

SUPERVISOR