DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Self Initiated Inspection

N672135382

FACILITY: A LINDBERG & SONS INC #83-99		SRN / ID: N6721
LOCATION: PN 3042 (2) CRUSHING PLANT #83-99, ISHPEMING		DISTRICT: Upper Peninsula
CITY: ISHPEMING		COUNTY: MARQUETTE
CONTACT: David Makinen , Foreman		ACTIVITY DATE: 06/08/2016
STAFF: Joe Scanlan	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Unannounced ins	pection to determine compliance with PTI# 83-99 and a	applicable Michigan Air Pollution Control Rules.
RESOLVED COMPLAINTS:	6	

INSPECTION DATE: 6/08/2016

DEQ STAFF: Joseph Scanlan, EQA

FACILITY: Portable Gravel Crusher

FACILITY OWNER: A. Lindberg & Sons

FACILITY CONTACT: Reed Alderton-- ralderton@lindberginc.com

<u>LOCATION</u>: The crusher was moved from Lindberg's 480 West Pit to the Paul Smith Pit off of Crestview Road in Forsyth Township.

INSPECTION: I wore steel-toed work boots, hardhat, high-visibility DEQ vest, safety glasses, and hearing protection. I parked my work vehicle in a location that was a safe distance away from the mobile heavy equipment (loaders) that were working on site and made myself visible to one of the loader drivers, Mr. Dave Makinen. Mr. Makinen was very cooperative and easily provided me with a copy of PTI# 83-99. Mr. Makinen said they had only crushed 7500 tons as they had been on site for just a few days. There were no fugitive dust issues that I observed and all equipment had visible identification numbers corresponding to PTI# 83-99 or other PTIs associated with Lindberg's crushers:

- Primary Crusher PC-11
- Conveyor CV-74
- Radial Stacker RS-19
- Screen SP-20
- Conveyor CV-15
- Cone Crusher CC-14

SUMMARY: I did not observed any violations of PTI# 83-99 or any applicable Michigan Air Pollution Control Rules.



Image 1(AL1) : PC-11 and SP-20



Image 2(AL2) : CC-14 and CV-15



Image 3(AL3) : Water truck providing adequate water -- no issues with spray bars or fugitive dust.



Image 4(AL4) : RS-19



Image 5(AL5) : CV-74

NAME Joseph

DATE 7/6/16 SUPERVISOR Dan W. Mali

http://intranet.deq.state.mi.us/maces/WebPages/ViewActivityReport.aspx?ActivityID=2458... 7/6/2016