DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY REPORT: On-site Inspection

N699972903

FACILITY: Lambda Energy Resources LLC - Mayfield 28		SRN / ID: N6999
LOCATION: Mayfield TWP, MAYFIELD		DISTRICT: Cadillac
CITY: MAYFIELD		COUNTY: GRAND TRAVERSE
CONTACT: Vickie Kniss , Regulatory Affairs		ACTIVITY DATE: 07/24/2024
STAFF: Tammie Puite	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: 2024 Compliance Inspection - Facility Shut In		
RESOLVED COMPLAINTS:		

Facility Description -

You access this facility by going North on M-37, North of Buckley and continuing East on West Center Road, off the 2nd curve of M-37, as you head North. Take West Center Road to Hannah Road and turn South. The Mayfield Township Hall is located at this intersection. Continue on Hannah Road South, once you have gone through a 90 degree curve, the access drive is to the West a few hundred feet south of the curve. The drive back in, is a maintained dirt track, and very scenic, making you think you are heading into a residence.

The active PTI is 219-01C. This facility is marked as an Opt-out source, with annual submission of emissions. But, it has been shut in since 2016.

Compliance Evaluation -

On July 24, 2024, Shane Nixon and I conducted an inspection of this source. The facility has birds making nests in the old equipment, and the beginnings of invasive vegetation starting to grow. The engine is shut in, with 2 - 24 inch sections of pipeline removed as well as a valve closed off. There appeared to be flow through the lines, which is consistent with previous notes and inspections. All production for this facility is being handled by the Mayfield 19 (B9162), which is an exempt facility. The Barrel Meter onsite showed 37273.9. I was unable to determine if the meter is working or not.

Summary -

I did not do a records request due to the long history of this facility being shut in and the 2023 emissions reporting showing zero throughput. Since this facility has been shut in since 2016, with no future plans to turn it back on, I will suggest that this facility be marked as a minor source and removed from emissions reporting. In the future, if the company would like to void the PTI, the facility would need to be rendered inoperable.