DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: CHEVRON MICHIGAN, LLC - THRIVE WEST/WARNER 2 CPF	SRN:	N7022
Location: Elmira Thrive West SW/4 SW/4, Sec. 5, T31N-R4W	District :	Gaylord
	County:	OTSEGO
[교통 기록	mpliance tus :	Compliance
Source Class: SM OPT OUT	staff: Becky	Radulski
	CE Completion	2/18/2014
Comments: FY14 scheduled inspection and records review		

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments	
02/18/2014	Scheduled Inspection	ion Compliance	scheduled inspection for FY14	
01/13/2014	MAERS	Compliance	see MAERS for comments	
12/19/2013	Other	Compliance	Records review for FY14 inspection	

Name: Becky Raduldi Date: 3/21/14 Supervisor:

Page 1 of 1