

DEPARTMENT OF ENVIRONMENTAL QUALITY  
 AIR QUALITY DIVISION  
 ACTIVITY REPORT: Self Initiated Inspection

N708828295

FACILITY: Chevron - Custer 15/20		SRN / ID: N7088
LOCATION: NW NW SE, SECTION 20, T29N-R7W, CUSTER TWP		DISTRICT: Gaylord
CITY: CUSTER TWP		COUNTY: ANTRIM
CONTACT:		ACTIVITY DATE: 01/14/2015
STAFF: Gloria Torello	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Site visit in response to the submittal of a MAP.		
RESOLVED COMPLAINTS:		

On January 14, 2015, staff from the Department of Environmental Quality (DEQ), Air Quality Division (AQD), visited the Custer 15/20 CPF in Chestonia Township in Antrim County, Michigan. Staff also reviewed the AQD files associated with SRN N7080. These actions were in response to Chevron's letter dated November 5, 2014 and the submittal of a malfunction abatement plan (MAP) for the Custer 15/20 CPF.

Based upon AQD's review, the AQD finds there is no active AQD permit associated with SRN N7080 and the Custer 15/20 CPF. Therefore the AQD will not send an approval letter for the MAP.

There is an active Caterpillar 3516 lean burn engine operating at the facility. Per Chevron's letter of 9/22/14 to the AQD, this engine is exempt per Rule 285(g). The AQD agreed with Chevron's 9/22/14 letter because on 10/1/14 the AQD voided permit 273-09.

The engine was operating at the time of the inspection. There were no visible emissions observed on the engine stack. The end of the stack extends above the building roofline. On site is a dehydrator, and one tank in a retaining area. The site is tidy.

NAME Gloria Torello DATE 1-15-15 SUPERVISOR 