

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

N732831665

FACILITY: MIDDLETONS MOULDINGS		SRN / ID: N7328
LOCATION: 575 RACE STREET, COLDWATER		DISTRICT: Kalamazoo
CITY: COLDWATER		COUNTY: BRANCH
CONTACT: James Brock, III, Plant Manager		ACTIVITY DATE: 10/06/2015
STAFF: Dennis Dunlap	COMPLIANCE STATUS: Unknown	SOURCE CLASS: MINOR
SUBJECT: Scheduled inspection.		
RESOLVED COMPLAINTS:		

This was not an announced inspection. Jamie Brock is the contact person. The inspection brochure was passed out. There is a New Building area and a Mill Building area. This is a Rule 208a source. However, this rule is going away and Middleton's need to conduct a Potential to emit calculation. They are having a consultant do this and will be sending this.

#### New Building

This building contains Stain Booths 4, 5, 7, 8 and 10. These are Rule 287(c) booths. Stain Booths 1, 2, 3, and 6 are no longer in operation. Stain Booth 7 showed 215 gallons of use for June, 2015. They are going to send information with gallons of stain minus water calculations to show compliance with Rule 287(c).

Other equipment includes Spray Booth #3 (Rule 287(c)), Rollcoater (Rule 287(c)), Top Coat Booths 1 and 2 (Rule 290), and a Stain Wiping operation (Rule 287(c)). Records show that these are in compliance.

There are two de-nib machines that have an inside dust collector. There are also a wide belt sander and a flat sander with an inside dust collector, Both of these are exempt by Rule 285(l)(vi)(B).

#### Mill Building

This building contains Spray Booths 1, 2, and 4 including the Lab Booth. These are Rule 287(c) booths. Usage amounts from Booth 4 need to be out from Booth 2 and they will be sending this information.

Also in this building are Linear Stain Booth #9 (Rule 287(c)) and UV vacuum coater. These are 3 units covered under Rule 287(c).

According to records these were in compliance.

There are three inside dust collectors for sanding equipment. These are exempt by Rule 285(l)(vi)(B).

There is an inside cyclone for metal working equipment. This empties into a 55 gallon drum. This is exempt by Rule 285(l)(vi)(B).

There is an outside dust collector that vents back inside the building. The sawdust is used for animal bedding. No visible emissions were seen. There appeared to be some sawdust on the ground. Mr. Brock thought that this was from the unloading of the silo that occurs about twice per week. The bags are checked periodically.

NAME

*Dennis Dunlap*

DATE

*11/19/15*

SUPERVISOR

*MB 11/19/2015*