## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

N736935710		SDN( / ID: N7260
FACILITY: International Mold Corporation		SRN / ID: N7369
LOCATION: 23224 GIACOMA COURT, CLINTON TWP		DISTRICT: Southeast Michigan
CITY: CLINTON TWP		COUNTY: MACOMB
CONTACT: Bryan Runstadler, Asst. Manager		ACTIVITY DATE: 07/26/2016
STAFF: Sebastian Kallumkal	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Onsite Inspection	· · · · · · · · · · · · · · · · · · ·	
RESOLVED COMPLAINTS:		

On Tuesday, July 26, 2016, MDEQ-AQD Staff Sebastian Kallumkal conducted an unannounced annual inspection at JAMS HOLDING DBA HERSH INDUSTRIES (N7369) located at 23224 Giacoma Court, Clinton Township, Michigan. The purpose of the inspection was to determine compliance with the Federal Clean Air Act; and Article II, Part 55, Air Pollution Control of Natural Resources and Environmental Protection Act, 1994 Public Act 451.

I arrived at the facility at about 2:55 PM. The building at this address showed the facility name as "International Mold Corporation (I. M. P.), Plant 1. I also observed other International Mold Corporation plants in the same street. I entered the Plant 1 building and met the receptionist. I introduced myself and stated the purpose of my visit. She told me Hersh Industries may have been moved out of the building about 10 years ago. She offered to contact a manager to assist in my inspection.

I met Mr. Bryan Runstadler, Asst. Manager. I introduced myself, showed my credentials and provided "DEQ Environmental Inspections: Rights and Responsibilities" brochure. During the pre-inspection meeting, he explained the facility's operations. International Mold Corporation has four plants on the same street under the same corporation. He told me that I.M.P. started its operations at this address about seven years ago.

Plant 1- 23224 Giacoma-Builds injection Mold and Blow Mold Parts (machining)

- **Plant 2- Plastic Injection molding Process**
- Plant 3- Injection Mold assembly
- Plant 4- Blow mold assembly

After the meeting he accompanied for an inspection of the Plant 1 facility. The Plant 1 machines and builds parts for injection molds and blow molds. It has 9 CNC machines. The coolant is recycled and the spent coolant is hauled off site. I did not observe any other process except plastic mold parts quality control lab. The CNC machines are exempt from permit to install (R336.1201) requirements pursuant to R336.1285(l)(vi)(B)- Equipment for ... Machining,... metals.... (B) Equipment has emissions that are released only into the general-in-plant environment.

He told me that Plant 1 has no emergency generators, cold cleaners (parts washers) or paint booths. I informed him that the other I.M.P. plants will be inspected at a later date to verify compliance. He provided me the contact name (David McKinnie, Purchasing, 586 783 6890; <u>dave.mckinnie@internationalmold.net</u>) to facilitate the inspection.

Conclusion: Based on the inspection International Mold Corporation-Plant 1 located at 23224 Giacoma Court, Clinton Township, Michigan appears to be in compliance with applicable air quality regulations. JAMS HOLDING DBA HERSH INDUSTRIES which was located at this address has been moved out few years ago or is out of business.

NAME <u>Sebartiany Kallumba</u> DATE 7/27/2016 SUPERVISOR

http://intranet.deq.state.mi.us/maces/WebPages/ViewActivityRe... 7/27/2016