

*Manla
Otsego*

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N746828277

FACILITY: BreitBurn Operating LP - NORTH HAYES 6 BSTR		SRN / ID: N7468
LOCATION: SEC 10 T30N R4W SE, GAYLORD		DISTRICT: Cadillac
CITY: GAYLORD		COUNTY: OTSEGO
CONTACT: CAROLANN KNAPP, ENVIRONMENTAL SPECIALIST		ACTIVITY DATE: 01/13/2015
STAFF: Shane Nixon	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: On site inspection		
RESOLVED COMPLAINTS:		

AQD staff traveled to Otsego County to perform an inspection at Breitburn's North Hayes Booster. The purpose of the inspection was to determine the facility's compliance with Permit to Install No. 219-05. Directions to the facility are: south on Hayes Tower Road to Van Tyle Road; west on Van Tyle Road to Coppins Road; south on Coppins Road to lease road; lease road south to the facility. Coordinates of the facility are 45.004N, -84.772W.

The facility consisted of a CAT 399 TA compressor engine. The engine was not operating at the time of the inspection. The exhaust piping from the engine to the stack was not installed. AQD staff observed the piping and the catalytic converter on the ground next to the compressor engine. Breitburn personnel indicated that the compressor engine has not operated in several years and MAERS data indicates that compressor has not operated since 2011. With the exception of the exhaust piping, the engine appeared to be maintained and ready for use should the need arise.

Based upon the on-site observations and review of MAERS data, AQD staff considers the facility to be in compliance with Permit to Install No. 219-05.

NAME *Shane Nixon*

DATE *1/14/15*

SUPERVISOR *[Signature]*