

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection *S*

N747624454

FACILITY: ALSONS		SRN / ID: N7476
LOCATION: 3010 W. MECHANIC ST., HILLSDALE		DISTRICT: Jackson
CITY: HILLSDALE		COUNTY: HILLSDALE
CONTACT:		ACTIVITY DATE: 02/25/2014
STAFF: Brian Carley	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled inspection		
RESOLVED COMPLAINTS:		

Company: Paragon Metals (parent company)
Contact: Jim Bondsteel
Email: Jim.Bondsteel@paragonmetals.com

I arrived at the facility to make an unannounced inspection. The building use to belong to Alsons, which was a faucet and shower head manufacturer, but now houses Paragon Metals. The office portion of the facility appeared to be unoccupied and I was finally able to find an employee who went and got Jim Bondsteel, who was the supervisor. I handed him the Environmental Inspections pamphlet and explained the purpose of my visit. Paragon took over the facility in 2012 and is a global manufacturer of precision engineered automotive and other industrial components. Alsons had a paint booth on site, which was exempt from needing an air permit, but it was no longer on site. I did not see any operations that would require this facility to apply for a Rule 201 air permit. I have determined that this facility is in compliance with the State of Michigan air rules. I thanked him for his time and left.

NAME *Brian Carley* DATE *3/10/14* SUPERVISOR *[Signature]*