

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N750839673

FACILITY: A & L IRON AND METAL INC.		SRN / ID: N7508
LOCATION: 2000 MILBOCKER RD., GAYLORD		DISTRICT: Gaylord
CITY: GAYLORD		COUNTY: OTSEGO
CONTACT: Brian Miller,		ACTIVITY DATE: 05/04/2017
STAFF: Becky Radulski	COMPLIANCE STATUS: Unknown	SOURCE CLASS: MINOR
SUBJECT: opacity reading for crusher engine		
RESOLVED COMPLAINTS:		

Stopped by while in area at 10 am; then again at 3:30 pm to view opacity from diesel engine that powers the crusher. Neither time was the crusher operating.

Emailed Brian Miller, and received this response 5/4/17, 7:43 pm: We are down and out for a little while. We are replacing the rotor at the moment. I will keep you posted on when they will be back up and running.

NAME Becky Radulski DATE 5/8/17 SUPERVISOR SN