

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N757357580

FACILITY: Automotive Lighting LLC		SRN / ID: N7573
LOCATION: 5600 BOW POINTE DRIVE, CLARKSTON		DISTRICT: Warren
CITY: CLARKSTON		COUNTY: OAKLAND
CONTACT: John McAuley , EHS Manager		ACTIVITY DATE: 04/07/2021
STAFF: Sebastian Kallumkal	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Onsite Inspection to verify dismantling of the equipment		
RESOLVED COMPLAINTS:		

On Tuesday, April 6, 2021, I, Sebastian Kallumkal, Michigan Department of Environment, Great Lakes & Energy (EGLE)-Air Quality Division (AQD) staff inspected Automotive Lighting LLC (N7573) located at 5600 Bow Pointe Drive, Clarkston, Michigan. The purpose of the inspection was to verify that the facility's operations at this location are ceased and process and control equipment are disconnected and permit to install PTI No. 152-17 can be voided. On March 2, 2021, AQD received a letter from John requesting to void the PTI.

At the facility, I met John. Due to Covid-19 protocol, the inspection was scheduled. I arrived at the facility around 10:45 AM. I completed facility's Covid-19 questionnaire and he took my body temperature. I observed that the front office and inside building are all empty. He accompanied me to the production area. Most of the process equipment are dismantled and gone. Some are being dismantled. Part of the RTO is still there but disconnected. They plan to vacate the building by April 15th of this year.

Today, I requested AQD Permit section to void the permit and send a copy of the void letter to John.

Conclusion: The facility ceased its operations at this location and production is moving to Tennessee. The permit can be voided.

NAME Sebastian KallumkalDATE 04/06/2021SUPERVISOR Joyce