

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N759050086

FACILITY: GLAWE INC		SRN / ID: N7590
LOCATION: 1010 US 23 North, ALPENA		DISTRICT: Gaylord
CITY: ALPENA		COUNTY: ALPENA
CONTACT:		ACTIVITY DATE: 08/22/2019
STAFF: Bill Rogers	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled minor source inspection		
RESOLVED COMPLAINTS:		

On August 22, 2019, I attempted to inspect Glawe Inc. at 1010 US 23 North, Alpena. The one permit still in effect at this site was a waste oil furnace at an equipment servicing facility.

In asking around, I was told that Glawe has gone out of business.

At 1010 US 23 North I found an office building known as 1010 Technology Center Inc. Ms. Mavis Desrocher, an employee there, told me Glawe was there long ago but it was torn down and replaced by a drive through bank office. The current building is the repurposed drive through bank. Heat is from natural gas fired furnaces. There is no vehicle servicing on site and no waste oil furnace.

I will notify Permits Section that Glawe is permanently closed, and we should void the applicable permits.

NAME William J Rogers L. DATE 8/28/19 SUPERVISOR SN