

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : ZF Axle Drives Marysville	SRN : N7795
Location : 2900 Busha Highway	District : Southeast Michigan
	County : SAINT CLAIR
City : MARYSVILLE State: MI Zip Code : 48060	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Sebastian Kallumkal
FCE Begin Date : 4/1/2015	FCE Completion Date : 8/20/2015
Comments : Facility appears to be in compliance with applicable air quality regulations.	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
07/30/2015	Scheduled Inspection	Compliance	Onsite Inspection
04/15/2015	MAERS	Compliance	MAERS Report; Submitted again on 4/14/2015 and 4/15/2015. Reviewed and uploaded.

Name: Sebastian Kallumkal

Date:

8/20/15

Supervisor:

CJE