

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
**ACTIVITY REPORT: On-site Inspection**

N779665875

<b>FACILITY:</b> DIVERSIFIED FUELS PROPERTIES LLC		<b>SRN / ID:</b> N7796
<b>LOCATION:</b> 810 OPDYKE RD, AUBURN HILLS		<b>DISTRICT:</b> Warren
<b>CITY:</b> AUBURN HILLS		<b>COUNTY:</b> OAKLAND
<b>CONTACT:</b>		<b>ACTIVITY DATE:</b> 12/27/2022
<b>STAFF:</b> Sebastian Kallumkal	<b>COMPLIANCE STATUS:</b> Compliance	<b>SOURCE CLASS:</b> MINOR
<b>SUBJECT:</b> Inspection to verify the soil/water remediation system is removed. Talked to Butrus Ghafari, GM 248 647 0020. He told me that gas station was constructed about 8 years ago. The gas station looked newer compared to the gas station seen via Google Map. I did not go to the back of the building to see if there is any system still there. The PTI can be voided based on the years the system had been there, based on the previous inspection in 2013 and that there is a new Mobil Gas Station. On February 6th, 2023, at about 12:00 Noon, I visited the location again. I drove around the facility (gas station). i did not see any soil/water (vapor) remediation process or equipment.		
<b>RESOLVED COMPLAINTS:</b>		

**Inspection to verify the soil/water remediation system is removed. Talked to Butrus Ghafari, GM 248 647 0020. He told me that gas station was constructed about 8 years ago. The gas station looked newer compared to the gas station seen via Google Map. I did not go to the back of the building to see if there is any system still there. The PTI can be voided based on the years the system had been there, based on the previous inspection in 2013 and that there is a new Mobil Gas Station.**

**On February 6th, 2023, at about 12:00 Noon, I visited the location again. I drove around the facility (gas station). i did not see any soil/water (vapor) remediation process or equipment.**

**PTI 152-07 can be voided.**

NAME Sebastian Kallumkal

DATE 02/07/2023

SUPERVISOR Joyce