N7866\_ FCE\_2015 0929 N7886 Marila Washtenaw

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

## **FCE Summary Report**

Facility:	Hyundai-Kia America Technical Center Inc. (HATCI)					TCI)	SRN:	N7886
Location :	6800 GEDDES RD						District	: Jackson
							County	: WASHTENAW
-	SUPERIOR TWP	State:	MI Z	ip Code :	48198	Comp Status		Compliance
Source Cla	ass: MAJOR					Staf	f: Dia	ne Kavanaugh-Vetort
• • • • • • • • • • • • • • • • • • • •						FCE Date	Completi	on 9/29/2015

## List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
09/22/2015	Scheduled Inspection	Compliance	Complete Scheduled inspection Title V Major ROP Facility. PCE of FCE.
09/18/2015	ROP Semi 1 Cert	Compliance	ROP 1st Semi-annual Cert/Dev Report for 2015. No deviations reported. Support included is a checklist/spreadsheet of entire ROP with compliance columns and remarks. FCE conducted FY15. Acceptable report.
05/19/2015	MAERS	Compliance	ROP Cert 3-5-14. Initial ROP 2014. Support docs attached. Used stack tested EF for CO and NOx for Engine Testing (controlled and uncontrolled testing RGs). All fuel throughput reported RGs AST/UST. Chassis reported. Emerg gens reported. CO 147 tons; NOx 6 tons; VOC 5 tons. 113 E3 gallons gasoline throughput.
03/09/2015	ROP Annual Cert	Compliance	1st time: ROP Annual and 2nd Semi Rept Cert & Deviation reports. No support. Normally submit support docs with MAERS; therefore will verify no deviations at that time.
03/09/2015	ROP SEMI 2 CERT	Compliance	1st time: ROP Annual and 2nd Semi-annual Report Cert & Deviation. Initial ROP issued 10/22/14. No support documents. Normally submit records with MAERS; will verify all at that time.

Name: Mulify With Date: 10/22/15 Supervisor: Page 1 of 1