## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**ACTIVITY REPORT: Scheduled Inspection** 

N797026888

FACILITY: BLARNEY CASTLE OIL - TUSTIN		SRN / ID: N7970
LOCATION: 20027 N MACKINAW TRAIL, TUSTIN		DISTRICT: Cadillac
CITY: TUSTIN		COUNTY: OSCEOLA
CONTACT: Erik Johnson , Environmental Manager		ACTIVITY DATE: 07/27/2014
STAFF: Rob Dickman	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT:		
RESOLVED COMPLAINTS:		

Inspected this source per General Permit number 31-08. The permitted equipment on site is used to remediate contaminated soil. There is one trailer on site which appears to house the collection equipment. It did not appear to be running at the time of the inspection.

This facility has not operated in the last 12 months (see attached email) and there are no plans for future operation. However, the permitted equipment is still on site and operable. It is recommended that the permit remain active