## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

## **FCE Summary Report**

Facility :	ty: Lambda Energy Resources, LLC - 35-12 Unit						SRN:	N8075
Location :	14696 M-65	South			*****		District :	Gaylord
							County:	ALPENA
City: L	ACHINE	State:	МІ	Zip Code :	49753	Comp Status		Compliance
Source Clas	ss: SM OP	TOUT				Staf	f: Bill Ro	gers
FCE Begin Date : 5/8/2018						FCE Date	Completion	5/8/2019
Comments	;							

## List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
05/08/2019	Scheduled Inspection	Compliance	Compliance inspection and record review
03/14/2019	MAERS		2018 MAERS, Check MAERS for any review comments

Name: William JR organs pate: 5/16/2019 Supervisor:

Page 1 of 1