

N8160
MANILA

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N816037746

FACILITY: SPEEDWAY SUPERAMERICA LLC #8801		SRN / ID: N8160
LOCATION: 31374 SCHOOLCRAFT RD, LIVONIA		DISTRICT: Detroit
CITY: LIVONIA		COUNTY: WAYNE
CONTACT: Jason D. Siemen , Environmental Representative		ACTIVITY DATE: 11/03/2016
STAFF: Jill Zimmerman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Target Inspection		
RESOLVED COMPLAINTS:		

DATE OF INSPECTION : November 3, 2016
 TIME OF INSPECTION : 8:30 am
 LEVEL OF INSPECTION : II
 NAICS CODE : 238290
 EPA POLLUTANT CLASS : VOC
 INSPECTED BY : Jill Zimmerman
 PERSONNEL PRESENT :
 FACILITY PHONE NUMBER : 616-954-7015, ext. 226

FACILITY BACKGROUND

The facility had operated an air stripper, soil vapor extraction systems, and air sparging systems, and the associated air pollution control devices at this gasoline filling station. The facility is located on the northeast corner of the intersection of Schoolcraft Road and Merriman Road in Livonia, Michigan.

COMPLAINT/COMPLIANCE HISTORY

No complaints have been received regarding this facility.

OUTSTANDING VNs

No violations have been issued regarding this facility.

PROCESS EQUIPMENT AND CONTROLS

The facility had been operating an unmanned air stripper, soil vapor extraction systems, and air sparging systems, and the associated air pollution control devices. This equipment would have been located onsite in a small trailer.

INSPECTION NARRATIVE

I arrived at the facility. I drove around the perimeter of the facility. There was no evidence of any remediation equipment at the facility. It appears that the equipment has been removed.

A meeting involving Mr. Michael Cox as well as staff from the MDEQ-AQD from the Warren District Office has been set for Friday November 4, 2016 to discuss the multiple sites where the remediation equipment has been removed.

APPLICABLE RULES/PERMIT CONDITIONS

The remediation equipment is operating under PTI 309-08, which was issued on September 29, 2008. There is one flexible group, which covered all of the remediation equipment.

On September 27, 2016 a letter was received from Speedway LLC requesting to void permit 309-08 because the equipment has been removed. An attached letter from Mr. Michael Cox with Practical Environmental Consultants, Inc. (PEC) stated that the remediation equipment had operated at this location between January 24, 2011 and June 30, 2011. This letter stated that the equipment had been removed from the site by July 5, 2011.

11/29/2016

Based on the correspondence received from the facility as well as the visual inspection, it appears that the remediation equipment has been removed from this location. This general permit will be voided since it has been verified that this equipment has been removed.

MAERS REPORT REVIEW

NA

FINAL COMPLIANCE DETERMINATION

At this time, the facility has removed all of the permitted equipment from this location. Permit 309-08 will be voided.

NAME 

DATE 11/29/16

SUPERVISOR 