DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: MONTMORENCY-OSCODA-ALPENA WASTE MANAGEMENT AUTHORI	SRN: N8248
Location: 6751 LANDFILL RD P.O.Box 13	District: Cadillac
	County: MONTMORENCY
1	ompliance Compliance tatus :
Source Class: MAJOR	Staff: Caryn Owens
0 0 11 10 10 10 10 10 10 10 10 10 10 10	FCE Completion 04-13-21 Date :
Comments :	

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments	
04/13/2021	On-site Inspection	Compliance	Onsite inspection & Records Review	
03/16/2021	ROP Annual Cert	Compliance	Annual, Semi Annual, and MAERS contained in one document. No deviations noted and this is typical for this source.	
03/16/2021	ROP SEMI 2 CERT	Compliance	Annual, Semi Annual, and MAERS contained in one document. No deviations noted and this is typical for this source.	
03/15/2021	ROP R215 Notification	Compliance	Change in RO From Albert LaFleche to Charles (Chuck) Varner	
03/11/2021	MAERS	Compliance	See MAERS for further Info.	
11/30/2020	ROP Other	Compliance	Tier 2 testing report. Report appears complete. Results indicate facility was at 2.872 Mg/yr, well below 50 Mg/year NMOC threshold pursuant to 40 CFR 60 Subpart WWW. Next time verify field data, & calibrations while on site.	
09/18/2020	ROP Semi 1 Cert	Compliance	1st semi annual Report, rec'd on time, no deviations reported	
08/12/2020	ROP Other	Compliance	NMOC Tier II Organic Compound sampling at MOA Landfill which is planned to be sampled in September 2020.	

Name:	Date:	Supervisor:	
		_	Page 1 of 1