

P0030
MAWILK

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

P003029811

FACILITY: Posen Construction Inc		SRN / ID: P0030
LOCATION: 12450 Sanders Street, DETROIT		DISTRICT: Detroit
CITY: DETROIT		COUNTY: WAYNE
CONTACT:		ACTIVITY DATE: 06/16/2015
STAFF: Terseer Hemben	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Concrete processing: Particulate Matter evaluation		
RESOLVED COMPLAINTS:		

Date of Inspection: June 16, 2015

SRN: P0030

Inspector: Terseer Hemben

Inspection Narrative

I visited two work locations that were previously registered to Posen Construction in the Wayne County for concrete processing in the city of Detroit, Michigan to conduct a scheduled compliance inspection. One of the sites was located at 7991 Hartwick Street, Detroit, and the second location was 12450 Sanders Street, Detroit. The purpose of visits to the sites was to evaluate particulate matter emissions attributed to the concrete process owned and operated by Posen Construction, Inc. Pre-inspection search indicated Posen Construction had set and operaed concrete business at the two sites in the last few years. The first point of call I made was 7991 Hartwick Street address. I arrived at the site at 1240 hours via Clay Street, northbound. I located the address on the right hand side of Hartwick Street. All gates leading onto the site were closed, chained and locked. There was no concrete equipment or Posen Construction sign on the facility. However, I sighted a gentleman working on the roof top of the building. I inquired if the facility belonged to Posen Construction. The gentleman informed the facility was owned by a business group that is yet to occupy the building. Posen Construction vacated the site many years ago.

I left the Hartwick address and drove to 12450 Sanders Street Detroit. The purpose of the visit to Sanders Street was to evaluate the particulate matter emissions attributed to the Posen Construction concrete process. I arrived at the site at 1430 hours. Findings indicated Posen Street had dismantled and removed all process equipment from the site. Weeds and grass were seen grown all over the site. I left the location at 1502 hours.

Determination

Visits were made to two site locations formerly occupied by Posen Construction for a scheduled compliance inspection. The inspection indicated Posen Construction no longer operated at the sites. There were no emissions from the two sites. Posen Construction was determined to be in compliance with Particulate Matter emission control.

NAME th

DATE 6/22/15 SUPERVISOR JK