DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Self Initiated Inspection

FACILITY: Arbor Operating Grand Canyon CPF		SRN / ID: P0268
LOCATION: NW SE SW SEC 32, VANDERBILT		DISTRICT: Gaylord
CITY: VANDERBILT		COUNTY: OTSEGO
CONTACT: Tim Rudolph ,		ACTIVITY DATE: 03/19/2015
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: review of stack and	odors	
RESOLVED COMPLAINTS:		

As follow up to VN sent in 2014 regarding stack on CPF having curved or candy cane shaped top, inspected facility to confirm curve section had been removed.

This facility also had odor complaints noted in January 2015.

During the inspection on 319/15, the stack now emits vertically with no obstruction. There were no odors or VE present from the stack or at the facility.

Radulai NAME T Sectur DATE 4 15 SUPERVISOR