

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
 ACTIVITY REPORT: Scheduled Inspection

P035825602

FACILITY: KRAKEN CRUSHED CONCRETE & RECYCLING - HIGHLAND PARK		SRN / ID: P0358
LOCATION: 14411 Oakland Ave, HIGHLAND PARK		DISTRICT: Detroit
CITY: HIGHLAND PARK		COUNTY: WAYNE
CONTACT:		ACTIVITY DATE: 06/05/2014
STAFF: Glen Erickson	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled inspection of portable concrete crusher located at the Calo Trucking yard off Chubb, just south of 6 Mile Rd.		
RESOLVED COMPLAINTS:		

Scheduled inspection of portable concrete crusher now located at the Calo Trucking yard on Chubb Rd. just south of 6 Mile Rd. intersection.

Met with plant operator Tony Macioci, Kraken Crushed Concrete & Recycling, LLC.

Plant was not operating at this time. Appears to have adequate spray arrays for good water coverage at multiple points in process. They utilize a water truck to supply the spray bars for control. The water truck is filled at the adjacent Calo Trucking operation.

Watering plant yard, which is unpaved, should be strait forward since yard is pretty small. Also, the prospect of truck track out is lessened by the fact that Chubb Rd. is gravel and there is about 200 yards of roadway until meeting with the paved 6 Mile Rd.

Power is provided by a new Detroit Diesel diesel-fired compression ignition engine and generator #06R1039235 set; 2013 model. Macioci claims the unit is a Tier III EPA certified engine, utilizing ultra low sulfur diesel fuel.

6-19-14: Briefly observed crusher in operation this morning as I drove down Chubb Road heading to Arbor Hills Landfill. Observed water spray misting above crusher, indicating good water control. No VEs. Plant yard produced no fugitive dust, due to slight rain occurring.

Consider plant is operating in compliance with their PTI No. 87-12.

NAME GLEN ERICKSON

DATE 6-24-14

SUPERVISOR [Signature]