DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

ACTIVITY REPORT: Scheduled Inspection

P047953882

FACILITY: COMPOSITECH		SRN / ID: P0479
LOCATION: 683 LINCOLN LAKE AVENUE SE, LOWELL		DISTRICT: Grand Rapids
CITY: LOWELL		COUNTY: KENT
CONTACT: Ken Fusee, General Manager		ACTIVITY DATE: 06/15/2020
STAFF: David Morgan	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT:		
RESOLVED COMPLAINTS:		

The following report documents Partial Compliance Evaluations conducted as part of a Full Compliance Evaluation for Industrial Services Group (ISG), formerly Compositech, located at 683 Lincoln Lake Avenue SE in Lowell. The purpose of the full compliance evaluation is to verify compliance with state and federal air pollution regulations as well as Permit to Install No. 172-13.

FACILITY DESCRIPTION

Historically, ISG consisted of filament winding, and molding equipment for the production of resin-based piping, storage tanks and custom designed process equipment. The facility is considered a synthetic minor source of hazardous air pollutants and volatile organic compounds under PTI No. 172-13. Currently there is no production equipment located at the facility.

COMPLIANCE EVALUATION

At 10:00 A.M. on January 30, 2020, AQD staff Dave Morgan and Kaitlyn DeVries conducted a site visit of ISG. At the time, there was no production occurring and a contractor indicated that the Plant Manager, Ken Fusee, was not on site. AQD staff did not enter the facility and departed the site.

On April 14, 2020, AQD staff Dave Morgan conducted a review of the company's 2019 submittal to MAERS. The company reported that the equipment was not used in 2019. It is also noted that in 2018, the company reported 0.56 tons of VOC and 1.1 tons of acetone which were well below limits of 11.2 tons and 3.0 tons, respectively, in PTI No. 172-13.

On June 8, 2020, AQD staff Dave Morgan had a telephone call with Ken Fusee, Plant Manager. In that call, Mr. Fusee indicated that all production equipment had been moved out of state. He indicated that he wanted to keep the permit active, however, he was advised that if equipment were relocated back to the site, a new permit may be needed. Due to coronavirus response guidelines, AQD staff requested Mr. Fusee provide photos documenting that the equipment had been removed. These are attached to this report.

SUMMARY

At this time, the company is in compliance with applicable requirements as the production equipment has been removed from the site. Until the PTI is voided, the company will remain in MAERS and subject to the Compliance Monitoring Strategy.




Image 1(Image 1): Image 1



Image 2(Image2) : Image2



Image 3(Image3): Image3




Image 4(Image4): Image4




Image 5(Image5): Image5




Image 6(Image6): Image6




Image 7(mage7): Image7

NAME David L. Morgan

DATE 6-17-20 SUPERVISOR