## DEPARTMENT OF ENVIRONMENTAL QUALITY

## AIR QUALITY DIVISION

## FCE Summary Report

Facility :	RIVERSIDE - SOUTH CHESTER - BIG BASS LAKE BOOSTER			SRN :	P0928
Location :	E 1/2 SE 1/4 SW 1/4 S	EC 1, T29N R2V	V	District :	Gaylord
				County :	OTSEGO
City: (	CHESTER TWP State:	MI Zip Code :	49735 Comp Status		Compliance
Source Cla	ss: SM OPT OUT		Staf	f: Sharor	n LeBlanc
FCE Begin	Date : 10/1/2022		FCE Date	Completion	10/26/2023
Comments	: FY 2024 FCE. sgl				

## List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments	
10/26/2023	On-site Inspection	Compliance	FY 2024 onsite inspection and records review. sgl	
02/24/2023	MAERS	Compliance	2022 MAERS, Facility uses a combination of manufacturer and maers EFs to determine emissions. Consistent with previous year. RICE MACT flagged. EU names are consistent with PTI. changes in control efficiencies resulted in differing changes in emissions from previous year. Check MAERS for any review comments	
12/01/2022 Other Non ROP		Compliance	CEDRI Annual Reporting for Subpart OOOa- see compliance activity report for summary	
12/01/2022	Other	Compliance	FY 2023 CEDRI submittal of Subpart OOOOa annual report. sgl	

Manaron & LeBlanc Date:

1-29-24

Thixon

Page 1 of 1