

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Demo/Reno Inspection

U17160116733679

FACILITY: Federal Plaza		SRN / ID: U171601167
LOCATION: 2901 I-75 Business Spur, Sault Sainte Marie		DISTRICT: Upper Peninsula
CITY: Sault Sainte Marie		COUNTY: Chippewa
CONTACT:		ACTIVITY DATE: 03/08/2016
STAFF: Joe Scanlan	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Unannounced inspection of scheduled demolition to determine compliance with asbestos NESHAP.		
RESOLVED COMPLAINTS:		

**ASBESTOS INSPECTION DATE:** 03/08/2016**DEQ-ASBESTOS NESHAP STAFF:** Joseph Scanlan**FACILITY:** Federal Plaza (strip mall)**FACILITY OWNER:** Central Savings Bank**ABATEMENT CONTRACTOR:** NA**ASBESTOS SURVEY:** Ryan Tucker, Western Upper Peninsula Abatement Co**DEMOLITION/RENOVATION CONTRACTOR:** Reid Contractors, Inc.**LOCATION:** 2901 I-75 Business Spur**DESCRIPTION:** Unoccupied strip mall

**INSPECTION:** This facility had been demolished prior to my arrival at the site. Start date was 3/01. The majority of the demolition work had been completed. There were some pieces of foundation slab and block and various bits of building material (ceramic tiles, foam insulation, etc.) remaining, however I did not notice any suspect asbestos containing material (ACM). There was an excavator on site still but it had not been run that day and there was no personnel on site. It appeared there had not been any activity the day of inspection. Notification suggests an asbestos survey was completed prior to demolition and there was no ACM discovered and/or in a large enough quantity to trigger the asbestos NESHAP.

**SUMMARY:** I did not observe any suspect ACM or violations of the asbestos NESHAP or Michigan Air Pollution Control Rules during this inspection.



**Image 1(fp1)** : Cleared and leveled demolition site



**Image 2(fp2)** : Former building site



**Image 3(fp3) :** Miscellaneous building debris, non-ACM

NAME Joseph S. [Signature]

DATE 3/15/16

SUPERVISOR \_\_\_\_\_