

STATE OF MICHIGAN

DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY



LANSING

November 17, 2020

UPS NEXT DAY DELIVERY

Mr. Erik Mayes Mayes Floor Covering 13044 Rosemary St. Detroit, MI 48213

ID: U632003160, Oakland County

Dear Mr. Mayes:

SECOND VIOLATION NOTICE

On August 31, 2020 and September 9, 2020, the Michigan Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD) performed an asbestos inspection at 15919 W. 10 Mile Road, Southfield, Michigan. The purpose of these inspections were to determine compliance with the requirements of Title 40 of the Code of Federal Regulations (40 CFR), Part 61, Subpart M (National Emission Standard for Asbestos), and Rule 942 of Part 55, Air Pollution Control of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended.

On October 12, 2020, the AQD sent a Violation Notice (VN) citing violations discovered because of the inspection and requested a written response by November 2, 2020. A copy of the VN has been enclosed for your reference. As of the date of this letter, the AQD has not received the written response.

Please be advised that failure to respond in writing and identifying actions taken to resolve the cited violation may result in an escalated enforcement action by the AQD. Please provide the information requested in the VNs dated October 12, 2020, by November 26, 2020, which corresponds to 14 days from the date of this letter.

The written response must be submitted to Mr. Jeffrey Benya, AQD, at EGLE, AQD, 3058 West Grand Boulevard, Suite 2-300, Detroit, Michigan 48202, and must include a copy to Mr. Jason Wolf, Enforcement Unit, AQD, at EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760. Or the response may be scanned and sent to benyaj@michigan.gov and wolfj2@michigan.gov.

Be further advised that issuance of this VN does not preclude or limit EGLE's ability to initiate any other enforcement action under state or federal law as appropriate.

Mr. Erik Mayes Mayes Floor Covering Page 2 November 17, 2020

If you have any questions regarding this matter or the actions necessary to come into compliance, please contact me at the number listed below.

Sincerely

Jeffrey J. Benya

Environmental Quality Analyst

Air Quality Division 313-618-0372

Enclosure

cc: Ms. Mary Ann Dolehanty, EGLE

Dr. Eduardo Olaguer, EGLE

Ms. Jenine Camilleri, EGLE

Mr. Christopher Ethridge, EGLE

Ms. Karen Kajiya-Mills, EGLE

Ms. Joyce Zhu, EGLE