

STATE OF MICHIGAN

DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY



DETROIT DISTRICT OFFICE

September 3, 2021

Mr. Tony Yearego Union Joints LLC 90 N. Main St. Clarkston, MI 48346

Mr. Robert Doran II Doran Excavating Inc. PO Box 141 Clarkston, MI 48347

Mr. Kevin Denha Lugo Properties LLC 700 N. Old Woodward Avenue, Suite 300 Birmingham, MI 48009

Mr. Yearego, Mr. Denha and Mr. Doran:

VIOLATION NOTICE

SRN: U632104211, Oakland County

On August 6, 2021, the Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD), conducted an inspection of the residential structures located at 960/972/984 Oxford and 1036/1046 Eaton, Berkley. These structures were being demolished as part of a commercial parking lot expansion project. The purpose of this inspection was to determine compliance with the requirements of Title 40 of the Code of Federal Regulations (CFR), Part 61, National Emission Standards for Hazardous Air Pollutants (NESHAP), Subpart M and Rule 942 of the administrative rules promulgated under Part 55, Air Pollution Control of the Natural Resources and Environmental Protection Act. 1994 PA 451, as amended.

According to our investigation, Union Joints LLC (1046 Eaton and all Oxford properties) and Lugo Properties LLC (1036 Eaton) owns the properties and Doran Excavating Inc. performed the demolition activities at the properties. The NESHAP for Asbestos holds both the owners and operator equally liable for violations.

During the inspection, AQD staff observed the following:

Five (5) residential structures at the same demolition site being demolished as part of a commercial parking lot expansion project. There was no Notification of Intent to Demolish on file and no asbestos survey information for the buildings was provided for the four (4) demolished structures. At the time of inspection three (3) homes had been completely demolished and disposed of. One (1) home was down and in a pile of rubble with an open hole (basement) and one (1) was standing and intact.

Mr. Tony Yearego, Union Joints LLC

Mr. Robert Doran II, Doran Excavating Inc.

Mr. Kevin Denha, Lugo Properties LLC

Page 2

September 3, 2021

| Process Description | Section Violated | Comments |
|---------------------------------------|---------------------|---------------------------|
| Demolition of four (4) residential | 40 CFR 61.145(b)(1) | Failure to provide 10 |
| structures (residential installation) | | working day notification. |
| to facilitate a commercial project | | |
| without a Notification of Intent to | | |
| Demolish/Renovate on file. | | |
| Demolition of four (4) residential | 40 CFR 61.145(a) | Failure to thoroughly |
| structures (residential installation) | | inspect for the presence |
| to facilitate a commercial project | | of asbestos containing |
| without conducting the required | | materials prior to |
| thorough asbestos surveys. | | demolition/renovation. |

Please initiate actions necessary to correct the cited violation and submit a signed written response to this Violation Notice by September 24, 2021 (which coincides with 21 calendar days from the date of this letter). The response should include: the dates the violation occurred; an explanation of the causes and duration of the violation; whether the violation is ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violation and the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

Please submit the written response to Jeffrey Benya at EGLE. AQD 3058 West Grand Boulevard, Suite 2-300 Detroit, Michigan 48202 or benyaj@michigan.gov and submit a copy to Mr. Jason Wolf, Enforcement Unit at EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760 or wolfj2@michigan.gov.

If any party believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide factual information to explain your position.

Thank you for your attention to resolving the violation cited above and for the cooperation that was extended to me during my inspection of the properties listed. If you have any questions regarding the violation or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely

Jeffrey J. Benya **Environmental Quality Analyst**

Air Quality Division

313-618-0372

Enclosures: NESHAP Fact Sheet, Sample results

Mr. Tony Yearego, Union Joints LLC Mr. Robert Doran II, Doran Excavating Inc. Mr. Kevin Denha, Lugo Properties LLC Page 3 September 3, 2021

cc: Ms. Mary Ann Dolehanty, EGLE Dr. Eduardo Olaguer, EGLE Ms. Jenine Camilleri, EGLE Mr. Christopher Ethridge, EGLE Ms. Karen Kajiya-Mills, EGLE Mr. Jason Wolf, EGLE Ms. Joyce Zhu, EGLE