

STATE OF MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY DETROIT



SRN: U821702318, Wayne County

May 23, 2017

Ms. Irene Tucker Detroit Land Bank Authority 500 Griswold Street, Suite 1200 Detroit, MI 48226

Mr. Tyrone Clifton Detroit Building Authority 1301 Third Street, Suite 328 Detroit, MI 48226

Mr. Butch Robinson Global Green Services Group 27113 Powers Dearborn Heights, MI 48125

Dear Ms. Tucker and Messrs. Clifton and Robinson

VIOLATION NOTICE

On May 17, 2017, the Department of Environmental Quality (DEQ), Air Quality Division (AQD), conducted an inspection of a residential property that had undergone a post-abatement, pre-demolition verification inspection in accordance with the agreement between the MDEQ Executive Office and the City of Detroit. Per the Renovation Notification the RACM was abated by Global Green Services on May 1, 2017. According to information provided by the Detroit Building Authority, the site had been inspected on May 10, 2017 and had been cleared for demolition.

Joseph Goeddeke of the MDEQ AQD conducted an inspection at 5544 McDougall St, Detroit on May 17, 2017. During the inspection, he collected two samples of flooring that tested positive for asbestos. The flooring was very friable. The asbestos abatement survey, conducted on July 11, 2016, identified multi-layer floor "over 1st/2nd basement windows on South side".

Process Description	Section Violated	Comments
Post abatement, post	§61.145(c)(1)	Failure to remove
clearance inspection		RACM

Please initiate actions necessary to correct the cited violation and submit a written response to this Violation Notice by June 13, 2017 (which coincides with 21 calendar days from the date of this letter). The written response should include:

Ms. Irene Tucker Mr. Tyrone Clifton Mr. Butch Robinson Page 2 May 23, 2017

- A copy of the asbestos survey;
- An explanation of the causes of the violations;
- A summary of the actions that have been taken and are proposed to be taken to correct the violation(s) and the dates by which these actions will take place; and
- What steps are being taken to prevent a reoccurrence.

If Detroit Land Bank Authority, the Detroit Building Authority and/or Global Green Service Group believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violations cited above. If you have any questions regarding the violation(s) or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely,

Joseph Goeddeke

Environmental Quality Analyst

Air Quality Division

517-331-7906

cc: Ms. LaReina Wheeler, City of Detroit BSEED

Mr. Melvin Butch Hollowell, City of Detroit

Mr. Timothy Palazzolo, DBA

Mr. Ron Crawford, DBA

Mr. Brian Farkas, DBA

cc via e-mail Ms. Lynn Fiedler, DEQ

Ms. Mary Ann Dolehanty, DEQ

Mr. Chris Ethridge, DEQ

Mr. Thomas Hess, DEQ

Ms. Karen Kajiya-Mills, DEQ

Ms. Wilhemina McLemore, DEQ