


STATE OF MICHIGAN

DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY





June 3, 2019

Mr. Leon Petty Go Green Contracting, Inc. 10301 Joy Road Detroit, MI 48204

Dear Mr. Petty:

SRN: U821901920, Wayne County

This letter supersedes the letter dated May 17, 2019, which incorrectly identified the property as 15972 Holmur, Detroit

VIOLATION NOTICE

On April 10 and 19, 2019, the Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD), conducted an inspection of the residential property located at 15792 Holmur, Detroit. The purpose of this inspection was to determine compliance with the requirements of Title 40 of the Code of Federal Regulations (CFR), Part 61, National Emission Standards for Hazardous Air Pollutants (NESHAP), Subpart M and Rule 942 of the administrative rules promulgated under Part 55, Air Pollution Control of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended.

According to our investigation, the Detroit Land Bank Authority owns the property and Go Green Contracting, Inc. performed the asbestos abatement activities at the facility. The NESHAP for Asbestos holds both the owner and operator liable for violations.

During the inspection, AQD staff observed the house was cleared for demolition. However, paper backing was found on the kitchen floor which tested positive for asbestos.

Process Description	Section Violated	Comments
Post abatement inspection at 15792 Holmur, Detroit.	40 CFR 61.145(c)(1)	Failure to remove RACM.

Please initiate actions necessary to correct the cited violation and submit a signed written response to this Violation Notice by June 24, 2019 (which coincides with 21 calendar days from the date of this letter). The response should include: the dates the violation occurred; an explanation of the causes and duration of the violation, whether the violation is ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violation and the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

Mr. Leon Petty Page 2 June 3, 2019

Please submit the written response to Ms. Tammy Bell at EGLE, AQD 3058 West Grand Boulevard, Suite 2-300, Detroit, Michigan 48202 or bellt4@michigan.gov and submit a copy to Mr. Jason Wolf, Enforcement Unit at EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760 or wolfj2@michigan.gov.

If Go Green Contracting, Inc. believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide factual information to explain your position.

Thank you for your attention to resolving the violation cited above and for the cooperation that was extended to me during our inspection of 15792 Holmur, Detroit. If you have any questions regarding the violation or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely,

Tammy Bell

Senior Environmental Quality Analyst

Air Quality Division 313-330-0105

Enclosure: Sample results cc: Mr. Tim Palazzolo, DBA

Mr. Paul Max, City of Detroit BSEED

Ms. Mary Ann Dolehanty, EGLE

Dr. Eduardo Olaguer, EGLE

Ms. Jenine Camilleri, EGLE

Mr. Christopher Ethridge, EGLE

Ms. Karen Kajiya-Mills, EGLE

Mr. Jason Wolf, EGLE

Ms. Wilhemina McLemore, EGLE