

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : Midwest Rubber Company	SRN : A6444
Location : 3525 RANGELINE RD P.O. Box 98	District : Saginaw Bay
	County : SANILAC
City : DECKERVILLE State: MI Zip Code : 48427	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Matthew Karl
FCE Begin Date : 4/4/2014	FCE Completion Date : 4/9/2019
Comments : FCE for 4/4/14-4/9/19, facility appears to be in compliance with PTI Nos. 136-17, 276-06, 259-04A, 376-97, 375-97B, 373-97, 567-94B, 196-87, 388-86, 387-86A, and 383-86.	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
02/26/2019	Self Initiated Inspection	Compliance	Self Initiated Inspection to determine compliance with PTI Nos. 136-17, 276-06, 259-04A, 376-97, 375-97B, 373-97, 567-94B, 196-87, 388-86, 387-86A, and 383-86.
02/03/2016	Scheduled Inspection	Non Compliance	Onsite inspection to evaluate compliance with Active PTIs: 383-86, 387-86, 388-86, 196-87, 567-94, 373-97, 375-97A, 376-97, 259-04, and 276-06
04/04/2014	MAERS	Compliance	MAERS audit completed 4/4/2014, no errors were found. glm

Name: Matthew R. Karl Date: 4/9/19 Supervisor: C. Hise