


DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
 ACTIVITY REPORT: Scheduled Inspection

N611943137

FACILITY: Core Energy LLC - Bagley 11		SRN / ID: N6119
LOCATION: NW/4, SE/4, SE/4, SEC 11, T30N, R3W, BAGLEY TWP		DISTRICT: Cadillac
CITY: BAGLEY TWP		COUNTY: OTSEGO
CONTACT: Bob Tipsword , Operations Manager		ACTIVITY DATE: 01/10/2018
STAFF: Rob Dickman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: SM OPT OUT
SUBJECT: Scheduled inspection of this opt out source.		
RESOLVED COMPLAINTS:		

Attempted to perform an onsite inspection of this facility. Records obtained from the facility indicated the facility was shut in some time prior to December of 2015. The purpose of the inspection was to obtain an inventory of equipment on site and to confirm that no equipment was operating.

There was a drilling rig in operation at the site. It was decided that the rig and the deep snow surrounding the facility made access to it unsafe. It is recommended that when the facility resumes operation, another inspection be performed.

NAME  DATE 1/25/18 SUPERVISOR 