

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection

N646945835

FACILITY: Breitburn Operating LP - Thompson #1		SRN / ID: N6469
LOCATION: Marilla Rd, CLEON TWP		DISTRICT: Gaylord
CITY: CLEON TWP		COUNTY: MANISTEE
CONTACT: Carolann Knapp, Environmental Specialist		ACTIVITY DATE: 08/29/2018
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: scheduled inspection		
RESOLVED COMPLAINTS:		

Traveled to N6469 Breitburn Operating Thompson 1 central production facility (CPF) to perform an inspection for FY18. This is a minor source. The facility is subject to PTI 154-98A.

The site is located on Marilla Rd, 0.5 miles north of Cadillac Hwy (M115) in Cleon Township, Manistee County. The access is a dirt road with a locked gate.

The source has been completely removed, including the building and tanks. The area where the building was is now a grassy field. A sign at the entrance still identifies this as the location for the Breitburn Thompson 1.

Breiburn indicated that the source was shut in more than 12 month prior to the removal of the equipment.

An email has been sent to Sue Thelen, AQD Permits, requesting the PTI be void.

An email has also been sent to the Oil, Gas and Minerals Division as a courtesy.

MACES will be updated to reflect the source as no longer operating.

NAME Becky RadulskiDATE 8/30/18SUPERVISOR SN