

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : RIVERSIDE - CLEAR LAKE CPF REVISED	SRN : N7631
Location : NE NW NW Section 35, T32N, R2E	District : Gaylord
	County : MONTMORENCY
City : HILLMAN State: MI Zip Code : 49709	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Sharon LeBlanc
FCE Begin Date : 10/11/2019	FCE Completion Date : 10/11/2021
Comments : 2022 FCE inspection and records review for decommissioned CPF, now acting as booster station.	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
10/11/2021	On-site Inspection	Compliance	Onsite inspection and data evaluation activities for FCE for FY 2022. Note Facility is no longer a CPF, as of Oct. 2020, has been shutting in and decommissioning equip and now acts as booster to another CPF. sgl
03/30/2021	MAERS	Compliance	2020 MAERS, Facility uses MAERS EFs to determine annual emissions. Note that facility removed one engine last year and another engine this year. Only one engine and dehy remains.
04/10/2020	MAERS	Compliance	2019 MAERS, Facility used only MAERS EFs to determine 2019 annual emissions. sgl
01/31/2020	Malfunction Abatement Plan	Compliance	PM/MAP updated to reflect new owner's maintenance practices. Following communications with facility, changes were made to page 7, Table 1 continued to reflect use of portable emission analyzer under the PM/MAP. Updated page was replaced in submittal. sgl

Name: _____ **Date:** _____ **Supervisor:** _____