

P1047
Mawila

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

P104749479

FACILITY: Classic Soft Trim		SRN / ID: P1047
LOCATION: 11891 Belden Court, LIVONIA		DISTRICT: Detroit
CITY: LIVONIA		COUNTY: WAYNE
CONTACT: George Walch , Manager		ACTIVITY DATE: 07/02/2019
STAFF: Todd Zynda	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: July 2, 2019 Inspection		
RESOLVED COMPLAINTS:		

Date of Investigation: July 2, 2019
 Date of Report: July 11, 2019
 Source: Classic Soft Trim
 SRN: P1047
 Address: 11891 Belden Court, Livonia, Michigan
 Facility Staff Present: George Walch, Manager
 DEQ-AQD Staff Present: Todd Zynda, Air Quality Division, Detroit District Office
 Time of Investigation: 3:15 PM to 3:25 PM

Summary of Facility Visit and Compliance Status:

Classic Soft Trim, located at 11891 Belden Court, Livonia, Michigan, was identified as a targeted inspection for 2019 due to the close proximity to ambient air trichloroethylene (TCE) concentrations that were detected as part of the Ford Beacon Project indoor air monitoring at addresses along Belden Court. For information regarding the ambient air sampling conducted as part of the Ford Livonia Transmission Plant remedial investigation, please see SRN A8645, MACES report CA_A864547612. There are no records of air quality permits on file for this facility.

On July 2, 2019 Mr. Todd Zynda arrived at 3:15 PM at 11891 Belden Court and was greeted by Mr. George Walch. According to Mr. Walch, operations at the location are mainly office space and a servicing area for the installation of leather interior and remote starts in vehicles. During the inspection the service area was observed with vehicles being worked on and car seats being reupholstered. The service area also included storage of upholstery material and other automotive electronics. The office area was not observed.

According to Mr. Walch, the facility does not operate any of the following equipment: boilers, cold cleaners, or emergency generators.

Operations at the facility do not appear to be subject to air quality rules or regulations. The source is considered to be in compliance for the reason that no air emissions activity occurs at this address.

NAME 

DATE 7/11/19

SUPERVISOR JK