

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

U8014389525241

FACILITY: System Components, Inc.		SRN / ID: U80143895
LOCATION: 1635 Stieve Dr., South Haven		DISTRICT: Kalamazoo
CITY: South Haven		COUNTY: VAN BUREN
CONTACT: Pete Murray , Plant Manager		ACTIVITY DATE: 05/23/2014
STAFF: Dorothy Bohn	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Unannounced inspection of a facility that the AQD has not been to before.		
RESOLVED COMPLAINTS:		

I arrived at 12:45 and left at 1:10. Ann Meskauskas with purchasing initially helped me and then towards the end of the tour, Mr. Murray showed up and completed the inspection. I did not give them an inspection pamphlet. The company has been here for 40 years and makes gear couplings.

The company has a number of mills, lathes, CNC machines and various other machining equipment. Everything vents inside the plant. They have one large, stubby stack on the east side of the building that they said was for ventilation in the newer part of the plant. They do not paint or heat treat. They do spray parts with a rust inhibitor.

I asked about the building at 76 Alyworth and Pete said that they have one person that works there to do surface grinding of parts. He said it does not vent out and has watered applied as they grind so it keeps the dust down. I did not observe this activity.

Everything appears to be exempt.

NAME Dorothy Bohn

DATE 5/30/14

SUPERVISOR MA 5/30/2014